

## Irvine Recliner

| Dimensions:       | Power Recliner | Recliner |
|-------------------|----------------|----------|
| Overall Height:   | 40½"           | 40½"     |
| Overall Depth:    | 38"            | 38"      |
| Overall Width:    | 31"            | 31"      |
| Seat Height:      | 20"            | 20"      |
| Seat Depth:       | 22"            | 22"      |
| Seat Width:       | 19½"           | 19½"     |
| Arm Height:       | 24"            | 24"      |
| Overall Reclined: | 67"            | 67"      |
| Wall Clearance:   | 18"            | 18"      |
| Chair Weight:     | 119 lbs.       | 104 lbs. |
| Weight Capacity:  | 350 lbs.       | 350 lbs. |
| COM Details*:     | 7 yds.         | 7 yds.   |



### Frames:

¾" plywood from managed sources. All joints are interlocking and/or glued, screwed and stapled for added strength and rigidity.

### Seat & Back Suspension:

Fully upholstered with a foam covering over a high-tensile-strength steel zig-zag sprung platform.

### Seat Cushion:

6" layer of 24 ILD/1.8 density high-resiliency foam wrapped in foam batting.

### Back Cushion:


Pillow back with blown foam fiber. Backrest cushions are attached.

### Nailhead Finishes:

Optional.




### Frame Finishes:




### Reclining Mechanism:

**Power Recliner:** Standard power-recline mechanism operated by a corded hand pendant.\*



**Recliner:** Standard 3-position push-back reclining mechanism.



### Floor Glides:

Metal

### Limited Warranty:

5-year limited warranty on frame and mechanism.  
1-year limited warranty on foam.  
Fabric manufacturer's warranty on fabric.

### Packaging:

Chair ships with backrest detached. Backrest is resting face down on top of the seat. Recliner is shipped inside of a box.

\* The estimated fabric requirement is based on 54"W material. The actual amount required may vary depending on pattern, pattern matching, material width or use of multiple fabrics.

\* **WARNING:** Do not lean too far forward when the recliner is reclined. This can cause the recliner to tip forward, and could result in injury to the resident and/or caregiver.