


Direct Supply®

INFRARED THERMOMETER

Quick-Start Guide to Taking a Temperature

1




Turn on the thermometer by pressing and releasing the Scan button.

2



Aim the thermometer at the middle of the forehead, approximately 1" to 2" away from the skin.

3



Press the Scan button to take a reading. The temperature will be displayed on the screen.

4



Turn off the thermometer by pressing and holding the Scan button for 5 seconds. The thermometer will automatically shut off after 60 seconds of inactivity.